

UBBN UNION BULLETIN BOARD NETWORK

390 WORTHINGTON RD.
WESTERVILLE, OHIO 43082
800-969-4702
www.ocsea.org

AUGUST 11, 2005

AN UPDATE FROM THE ODOT STATEWIDE LABOR/MANAGEMENT
HEALTH AND SAFETY COMMITTEE

Current ODOT safety issues and information under consideration:

Dump truck lighting:

Strobe lights on cabs may need relocated if less than 3/4 of the lens is visible when standing 30 feet behind the rear of the truck with the bed down.

Truck Mounted Attenuators:

TMA's are not mandatory when setting up work zones; they are optional.

Confined Space Program:

This program is currently being reviewed by the districts.

Flagging:

A new flagging class will be available in the near future.

Lockout/Tagout:

The design of this program is complete and has been sent to the district Safety Offices. District Safety Representatives will make arrangements for training the affected personnel.

Public Employee Risk Reduction Program (PERRP):

This program has received a good response. Inspections of ODOT facilities and work zones are being carried out.

Violence in the Workplace Policy:

This policy is currently being updated.



PRINTED IN-HOUSE BY

OCSEA
OHIO CIVIL SERVICE EMPLOYEES ASSOCIATION
AFSCME LOCAL 11 AFL-CIO

**For any questions please contact
your Union District Health and
Safety Representative.**